I hereby certify that this paper (along with any paper referred to as being attached or enclosed) is being transmitted via the Office electronic filing system in accordance with § 1.6(a)(4).

Dated: 7/21/0X

Signature: // (Milena Sukovic)

Docket No.: 06005/36796

(PATENT)

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Letters Patent of:

Daniel D. Christensen et al.

Patent No.: 6,912,671

Issued: June 28, 2005

For: WIRING FAULT DETECTION, DIAGNOSIS

AND REPORTING FOR PROCESS CONTROL

SYSTEMS

REQUEST FOR CERTIFICATE OF CORRECTION PURSUANT TO 37 CFR 1.322

Attention: Certificate of Correction Branch

Commissioner for Patents

P.O. Box 1450

Alexandria, VA 22313-1450

Dear Sir:

Upon reviewing the above-identified patent, Patentee noted typographical errors which should be corrected.

In the Claims:

Claim 1; Column 15, lines 52-53; Applicant error; "a wiring fault detection unit and a wiring fault detection unit" should be -- a wiring fault detection unit and a diagnostic manager --.

Claim 10; column 16, lines 35-36; Applicant error, "a wiring fault detection unit and a wiring fault detection unit" should be -- a wiring fault detection unit and a diagnostic manager --.

The errors were found in the application as filed by applicant. Please charge our credit card in the amount of \$100.00 covering the fee set forth in 37 CFR 1.20(a).

Patent No.: 6,912,671 Docket No.: 06005/36796

The errors now sought to be corrected are inadvertent typographical errors the correction of which does not involve new matter or require reexamination.

Transmitted herewith is a proposed Certificate of Correction effecting such amendment. Patentee respectfully solicits the granting of the requested Certificate of Correction.

The Director is hereby authorized to charge any deficiency in the fees filed, asserted to be filed or which should have been filed herewith (or with any paper hereafter filed in this application by this firm) to our Deposit Account No. 13-2855, under Order No. 06005/36796.

Dated: 7/22/08

Respectfully submitted,

Milena Sukovic

Registration No.: 60,532

MARSHALL, GERSTEIN & BORUN LLP

233 S. Wacker Drive, Suite 6300

Sears Tower

Chicago, Illinois 60606-6357

(312) 474-6300

Attorney for Applicants

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO. 6,912,671

APPLICATION NO. 09/850,300

ISSUE DATE June 28, 2005

INVENTOR(S) Daniel D. Christensen et al.

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Claims:

At Column 15, lines 52-53, "a wiring fault detection unit and a wiring fault detection unit " should be - a wiring fault detection unit and a diagnostic manager --.

At Column 16, lines 35-36, "a wiring fault detection unit and a wiring fault detection unit " should be - a wiring fault detection unit and a diagnostic manager --.

PTO/SB/44 (09-07)
Approved for use through 08/31/2010. OMB 0651-0033
U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page _1_ of _1

PATENT NO.

6,912,671

APPLICATION NO.

09/850,300

ISSUE DATE

June 28, 2005

INVENTOR(S)

Daniel D. Christensen et al.

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Claims:

At Column 15, lines 52-53, "a wiring fault detection unit and a wiring fault detection unit " should be - a wiring fault detection unit and a diagnostic manager --.

At Column 16, lines 35-36, "a wiring fault detection unit and a wiring fault detection unit " should be - a wiring fault detection unit and a diagnostic manager --.